

shall be inspected and shall be pumped to remove any solids if present. Excess traffic in the mound area shall be avoided.

History: Cr. Register, December, 1980, No. 300, eff. 1-1-81; renum. from H 63.23, Register, June, 1983, No. 330, eff. 7-1-83; am. (1)(b) 1, 2, and 3, Register, June, 1991, No. 426, eff. 7-1-91.

CHAPTER 83

INDUSTRY, LABOR AND HUMAN RELATIONS

CHAPTER 83

INDUSTRY, LABOR AND HUMAN RELATIONS

CHAPTER 83

CHAPTER 83

INDUSTRY, LABOR AND HUMAN RELATIONS

CHAPTER 83