

(The foregoing lists are for illustrative purposes only, and are not meant to be all inclusive.)

History: Cr. Register, September, 1956, No. 9, eff. 10-1-56.

Chir 3.06 Unprofessional conduct. The practice of chiropractic regularly in living quarters (bedside care excepted) as well as the maintenance of an unsanitary office or equipment shall be considered to be unprofessional conduct within the meaning of sec. 147.25, Wis. Stats.

History: Cr. Register, August, 1959, No. 44, eff 9-1-59.

Chir 3.07 Radiation. (1) All x-ray equipment must be of shock-proof construction.

(2) Lead cones or diaphragms should be used to confine the primary ray within the film area to reduce the secondary radiation to a minimum.

(3) A 2.5 m.m. external filter should be used on all x-ray tubes.

(4) Lead screen, or, preferably, lead lined booth with sufficient thickness, 1/16 inch lead.

(5) X-ray equipment should be located as to direct all primary rays to the outside or away from any occupied adjacent rooms.

(6) Lead, leaded material, steel, or concrete of sufficient thickness must be used where needed to protect persons in living quarters or adjacent offices in accordance with table on page 15 of the X-Ray Protection Handbook, No. 60, which is available for 20¢ in coin from the National Bureau of Standards, Department of Commerce, Government Printing Office, Washington, D. C.

History: Cr. Register, August, 1960, No. 56, eff. 9-1-60.